

Fire Inspections NovemberDecember 2020

Agenda

- Welcome and Introductions
- License Registration
- Impairment Tags
- Inspections and Scheduling
- **Q&A**



Presenters

- Kelly Turner
- -Captain in Fire Prevention 8 years, Fire Department 22 years
- Shirley Guzman
- Senior Development Services Specialist-14 years
- Michael Bolt
- Business Analyst for Build SA project

Fire Systems Inspections

_		
HANSEN		ACCELA
	Underground Fire Line	
FDUGVISUAL	onder ground in the Enre	Fire -Visual Inspection
FDUGHYDRO		Fire-Hydro Inspection
FDUGFLOW		Fire- Hydrant Flow Inspection
FDUGFLUSH		Fire- Flush Inspection
FDUGFLUSH	**NEW**	·
		Underground Final Inspection
	Sprinkler/Standpipe	
FDFSVI<100		Fire Visual Inspection
FDFSVI>100		Fire Visual Inspection
FDFSHYDRO		Fire-Hydro Inspection
FDFS24HRAIR	**NEW**	Fire-24 Hour Air Test Start Inspection
1 DI SZHINAIN	TVLVV	Fire-24 Hour Air Test Start Inspection
	NEW	Inspection
FDFSFLOW		.,
FDFSFLUSH		Fire- Flush Inspection
FDFSHILOW		Fire-High/Low Test Inspection
FDFSMAINDR		Fire-Main Drain Test Inspection
FDFSPUMP		Fire- Pump Test Inspection
FDFSTAMPFL		Fire-Tamp/Flow Test Inspection
FDFSTRIP		Fire- Trip Test Inspection
	NEW	Fire-Deluge Inspection
	NEW	Fire-Pre-action System
FINALFS		Fire-Sprinkler Final Inspection
	NEW NAME	Fire-Standpipe Pump Inspection
	NEW	Fire-Standpipe Final Inspection
	Fire Alarm	
FINAL FA		Fire-Alarm Inspection
	Gaseous Suppression	
FGSSFINAL		Fire-Gaseous Suppression Inspection
I GSSI IIVAL	Fired Father and able to	The Gaseous Suppliession Inspection
	Fixed Extinguishing System	
FPSTEST		Fire-Fixed Extinguishing System
	Spray Booth Permit	
FSPRAYBTH		Fire- Spray Booth Inspection

Old Way-Hand Written Activity Sheet

- Handwritten Activity
 Sheet
- Can be easily lost

Accela-Emailed Activity Report

- Emailed to the applicant with notification of inspection status-Passed, Partial Pass, Phased Pass, Failed
- Includes inspector result comments

Inspection Activity

HansenSigned Permit

		RMIT				
	CITY OF:	OINOTNA NA 2	SANAN	SIONIO		
	FIRE PREVI	ENTION DIVISION	(Q	\mathfrak{D}		
	1901 530.7	TH ALAMO STREET	Table			
	\$40.40	AT COMES, T. J. TRACE	Robert	100		
	(110) 1014.	ID Red: (110) 107-79-9				
PERMIT HO. PERMIT TYPE		BUSINESS/ORGANIZATION	DATE	EXPIRATION DATE		
t4rfit4 FIRE SPRINKLER	SYSTEM	ABBEYAT SONTERRA	1581818			
PERMIT LOCATION		CONTRACTOR				
:=1 to HUESNER BAN ANTONIO c25c-eeee	NTONIO 142 IS CIESTFAIR CIEST					
icz) (* 4000 SLDG (* (FIRE (JALL AREA *) *E OPTION JAWES R GRIFFITH JI	i PE 2 1	HOUSTON TX				
	•					
TYPE OF WORK NE()						
TYPE OF WORK NE() HUBBER OF FLOORS: 4 HO. OF PERBIT SYSTEM SATEUIC OF PERBIT SYSTEM OF PERBIT SYST	E3/HE A03 : 482	1901-1733 (2001-104) 1811-1733 (2001-104) 1821-1833 (2001-104)				
TYPE OF WORK NE() HUBBER OF FLOORS: 4 HO, OF PRINTS YSTEM SATELY, WYSTEM TO EXTRA YSTEM SATELY, WYSTEM SATELY,	53/HE/03: 482 .000710038 / 1910290110 27746091,0110009904					
TYPE OF WORK NEU HIB BER OF FLOORS: 4 HO OF PERBIT SYSTEM SIDEUIC Y VERLICET 100-2004 PROSES PT 0 (044) HO OF PERBIT SYSTEM SIDEUIC TO (044) HO OF PERBIT SYSTEM SIDEUIC TO (044)	SAME AOS : 482 .0007103 31 01 10 10 20 01 10 .770000 1,01 10 20 04 04 10 FIRE SE	*6>360 LOCA (101*,13 OCSSAY OSAY (68)	1013 7EXM FOX 10E	P3 10LL6 110P		
TYPE OF MORN NE() UBUBER OF FLORE: 1. UBUBER OF FLORE: 1. VISUALE: INC. METER SAFEUR VISUALE: INC. METER SAFEU	SMEADS: 452 .000710310 PTCPATE .7700041,0110004050 FIRE SF	*ANKLER SYSTEM	1013 7EEG FOX 10E	P3 16LL6 110P		
TYPE OF WORK NEU UNI BER OF FLOORS: 4 LO OF PREMIT THE SIDEWING WY VISUAGE (SECTION 1980 PAPER OF WY VISUAGE OF WY VISUAGE BUT TAKEN I SOLLAND (SECTION 1981 PAPER OF BUT TAKEN I SOLLAND (SECTIO	53/HE/403 : 487 .0007160 31 - 119 16294 119 FIRE SF 1007782351 31 - 144, 11843 1007782351 31 - 144, 11843 10078824 119 100	**************************************	013 7ED3 FOX 10E1 011 07711C0 8EE 3EBU 12E 10E710CE 0F 0FF 8 YEES 30011 COST. 5 0F0 0FY 0 10EST.	P3 10114 110P L4 110P3 LUCEP3E OU 1 10E		
PRE OF WORK NEU UNBERT OF FLOORS: 4 OU OF PERSIST SYSTEM SOCIOUS TO VISUACE I (SCIENCE) (SCIENCE STANDING ST	53/HE/403 : 487 .0007160 31 - 119 16294 119 FIRE SF 1007782351 31 - 144, 11843 1007782351 31 - 144, 11843 10078824 119 100	**************************************	013 7E23 FOX 10E1 011 07711C0 BLE TEAU 12 E 10E714 CE OF AP** 0 PEES 300 LL COSTY 3 APO APY 6 10E214 0 E 677750 * LO 714 PS	P3 10114 110P L4 110P3 LUCEP3E OU 1 10E		
PRE OF WORK NEU UNBERT OF FLOORS: 4 OU OF PERSIST SYSTEM SOCIOUS TO VISUACE I (SCIENCE) (SCIENCE STANDING ST	53/HE/403 : 487 .0007160 31 - 119 16294 119 FIRE SF 1007782351 31 - 144, 11843 1007782351 31 - 144, 11843 10078824 119 100	**************************************	013 7E23 FOX 10E1 011 07711C0 BLE TEAU 12 E 10E714 CE OF AP** 0 PEES 300 LL COSTY 3 APO APY 6 10E214 0 E 677750 * LO 714 PS	P3 10114 110P L4 110P3 LUCEP3E OU 1 10E		
CYPE OF WORST NEU UNID BER OF FLOORS : 4 (IN OF PERSIT IS THE SIDE UNIV.	53/HE/403 : 487 .0007160 31 - 119 16294 119 FIRE SF 1007782351 31 - 144, 11843 1007782351 31 - 144, 11843 10078824 119 100	RINKLER, SYSTEM LISTINGER SYS	013 7E23 FOX 10E1 011 07711C0 BLE TEAU 12 E 10E714 CE OF AP** 0 PEES 300 LL COSTY 3 APO APY 6 10E214 0 E 677750 * LO 714 PS	P3 10114 110P L4 110P3 LUCEP3E OU 1 10E		
TYPE OF WORK NEU UUU BER OF FLOORS: 4 LOO FPENENT STATE SADEWING WY VISUAGE 186.700**180.700 FFENENT WY MISSIAGE 186.700**180.700 FFENENT WY MISSIAGE 186.700**180.700 FFENENT BOOK NEWS 186.700 FFENEN	53/HE/403 : 487 .0007160 31 - 119 16294 119 FIRE SF 1007782351 31 - 144, 11843 1007782351 31 - 144, 11843 10078824 119 100	**************************************	013 7E23 FOX 10E1 011 07711C0 BLE TEAU 12 E 10E714 CE OF AP** 0 PEES 300 LL COSTY 3 APO APY 6 10E214 0 E 677750 * LO 714 PS	P3 10114 110P L4 110P3 LUCEP3E OU 1 10E		
CYPE OF WORST NEU UNID BER OF FLOORS : 4 (IN OF PERSIT IS THE SIDE UNIV.	53/HE/403 : 487 .0007160 31 - 119 16294 119 FIRE SF 1007782351 31 - 144, 11843 1007782351 31 - 144, 11843 10078824 119 100	RINKLER, SYSTEM LISTINGER SYS	013 7E23 FOX 10E1 011 07711C0 BLE TEAU 12 E 10E714 CE OF AP** 0 PEES 300 LL COSTY 3 APO APY 6 10E214 0 E 677750 * LO 714 PS	P3 10114 110P L4 110P3 LUCEP3E OU 1 10E		

BuildSALetter of Completion

Ţ	1361 South Alamo Street San Antonio, Texas 78204 TTER OF COMPLETION julied reviews and inspections are satisfactorily performed for FIR-FSS-PMT20-22600382 2200 DANBURY
We are pleased to inform you that all reg the following permit	TTER OF COMPLETION juried reviews and inspections are satisfactorily performed for FIR-FSS-PMT20-22500382
We are pleased to inform you that all reg the following permit	jured reviews and inspections are satisfactorily performed for FIR-F38-PMT20-22500382
We are pleased to inform you that all reg the following permit	jured reviews and inspections are satisfactorily performed for FIR-F38-PMT20-22500382
We are pleased to inform you that all reg the following permit	jured reviews and inspections are satisfactorily performed for FIR-F38-PMT20-22500382
the following permit	FIR-F38-PMT20-22500382
the following permit	FIR-F38-PMT20-22500382
PERMIT NUMBER	
PERMIT NAME	2200 DANBURY
PERMIT NAME	
	2200 DANDORT
PERMIT ISSUANCE DATE	02/07/2020
DATE	
LOC ISSUANCE	
DATE	
ADDRESS	2200, DANBURY, City of San Antonio TX 78217
DESCRIPTION OF	
WORK	
Thank you for your business	
The Charles Advantage	
The City of San Antonio	
Padracing with our	r community to build and maintain a safer San Antonio

Top Thing to Know-Automatically issued and EMAILED to applicant on the permit after ALL inspections have PASSED

Inspection Scheduling


Current Scheduling Method

- Call in to 207-8410
- Wait on hold for the next agent
- Verbal only scheduling verification


New Online Option

- Online scheduling via Accela Citizen Access
- Immediate scheduling
- Email confirmation

On Site Contact



Add Notes for Inspector



Inspection Request

After Hours Inspections

Process remains the same

Email request form to:

fireinspections@sanantonio.gov

Fire Life Safety Reporting

- License Registration will be required for impairment tag reporting(Red and Yellow)
- Impairment tag reporting is available through the Accela Citizen Access Portal
- Impairment Report must be included in the submission
- Impairment Correction report is required to be submitted to clear the impairment.

Periodic Inspections

 In the near future, reports from annual inspections, 5 year tests, etc. will be submitted to the Fire Marshal's office through Accela Citizen Access.

Topic: Fire Systems: Creating the Fire LP Record	Nov. 17, 19, 23, 25 Dec. 1, 3	2 PM - 3 PM	1]
WebEx Click Here			
Calling In?_			
Use the following information to			
access the meeting:			
Phone Number: 1-415-655-0001			
Meeting Number: 1774775448			
Course Description:			
This course walks the participant			
through the online portal to select the			
Fire LP record-type, complete all			
required information on the			
application and final submittal.			

Questions



